

KEY

————————	Ground surface based on topographic surveys by Department of Water Resources in July 2000 and February 2006.
- - - - - - - - - - - - - - - -	Appoximate ground surface estimated from a limited number of hand-held altimeter points.
— — ? — — ? — —	Geologic contact, uncertain.
←	Sense of landslide movement.

Quad	Undifferentiated alluvium and rock fall debris, includes basalt blocks of various sizes
Qd/Qls	Rock fall/landslide debris, includes basalt blocks of various sizes
Tl	Lovejoy Basalt
Kc	Chico Formation

Note: See Drawing 1 for location of section.

Issue No.	Description	Date	Drwn.	Chkd.	Resp. Engr.	Proj. Mgr.

SAGE
SANDERS & ASSOCIATES
GEOSTRUCTURAL ENGINEERING, INC.
Geotechnical • Structural • Geological
www.sandersgeo.com
No. California
4180 Douglas Bl., Ste. 100
Granite Bay, CA 95746
P (916) 729-8050
F (916) 729-7706
So. California
540 S. El Molino Ave.
Pasadena, CA 91101
P (626) 792-8151
F (626) 792-8440

HDR
HDR Engineering, Inc.

BAR LENGTH ON ORIGINAL DRAWING EQUALS ONE INCH. ADJUST SCALE ACCORDINGLY.

Project Manager: S. Planck
Designed: D. Kennedy
Designed:
Checked: D. S. Kieffer
Drawn: G. Baker

Evaluation of Iron Canyon for Proposed Fish Ladder Structure Repair and Construction

Big Chico Creek in Upper Bidwell Park

Chico Butte County California

SCHEMATIC GEOLOGIC CROSS SECTION A-A'

Date: 5/24/06
Scale: 1" = 60'
Project No.: SE05-071
File Name: SECTIONS.dwg
Drawing No.: 5
Issue

F:\1-PROJECTS\2005\05-071 Iron Canyon Fish Passage\AUTOCAD\SECTIONS.dwg, 5/24/2006 4:01:11 PM, gbaker