

City of Chico 2014 Tree Removal List

0 Extreme
 1 High
 2 Moderate

Address	Location:	zone	Species:	Height	DBH	Notice	Marked	Notes:	Priority Rating	Cost
Priority 1 Trees November 2014										
862 E 19th St	F:1	1	Chinaberry	30	30	yes	yes	Extensive decay in main trunk	1	500
862 E 19th St	F:2	1	Chinaberry	30	25	yes	yes	Extensive decay in main trunk	1	500
352 E 20th St	S:3 Hemlock	1	Black Walnut	50	35	yes	yes	Extensive decay in main trunk and roots	1	500
1159 Oakdale	S:1 W 12th	1	Silver Maple	35	12	yes	yes	Dying, dead tops leaning toward power lines	1	500
1041 Poppy St	F:1	1	Black Walnut	45	31	yes	yes	Dead (AAA Property Mang. 530-895-3500)	1	500
1408 Dayton Rd	S:1 Poppy St	1	Black Walnut	45	35	yes	yes	Dying	1	500
1417 Broadway	F:1	1	English Walnut	40	38	yes	yes	Decay in main trunk and upper scaffolds	1	500
122 W 14th St	F:2	1	Silver Maple	45	28	yes	yes	Dying, decay	1	500
1405 Normal Ave	F:1	1	Silver Maple	50	27	yes	yes	Dying, extensive decay in main trunk	1	500
1405 Normal Ave	F:2	1	Silver Maple	55	19	yes	yes	Dead	1	500
1415 Normal Ave	F:1	1	Silver Maple	55	24	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Zelkova	25	10	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Tulip	45	12	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Tulip	55	15	yes	yes	Dying	1	500
LCC Greenway Triangle	see map	1	Tulip	50	14	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Pin Oak	40	12	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Pin Oak	45	13	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Tulip	45	11	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Hackberry	30	13	yes	yes	Dying, invasive species	1	500
LCC Greenway Triangle	see map	1	Red Cypress	45	25	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Red Cypress	55	26	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Hackberry	40	19	yes	yes	Dying, invasive species	1	500
LCC Greenway Triangle	see map	1	Red Cypress	40	3x9"	yes	yes	Dying	1	500
LCC Greenway Triangle	see map	1	Red Cypress	40	multi 10	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Red Cypress	40	21	yes	yes	Dead	1	500
LCC Greenway Triangle	see map	1	Red Cypress	40	22	yes	yes	Dead	1	500
1504 Laburnum Ave	S:1 5th Ave	5	Silver Maple	55	20	yes	yes	Dead	1	500
1504 Laburnum Ave	S:2 5th Ave	5	Silver Maple	55	23	yes	yes	Dead	1	500
1504 Laburnum Ave	S:4 5th Ave	5	Silver Maple	60	23	yes	yes	Dead	1	500
1480 Palm Ave	F:1	5	Black Walnut	40	31	yes	yes	Dead	1	500
1222 W 11th Ave	F:1	5	English Walnut	40	32	yes	yes	Extensive dieback,decay at old heading cuts	1	500
211 W 1st Ave	F:1	5	Modesto Ash	55	29	yes	yes	Extensive trunk defects, weak attachments	1	500
211 W 1st Ave	F:2	5	Modesto Ash	55	30	yes	yes	Extensive trunk defects, splitting	1	500
376 Vallombrosa Ave	F:1	5	Chinese Pistache	45	20	yes	yes	Dead	1	500
294 E 3rd Ave	S:1 Laburnum	5	Golden Rain	50	26	yes	yes	Decay in main trunk and upper scaffolds	1	500
1280 W Sacramento Ave	F:1	5	English Walnut	35	18	yes	yes	Dead	1	500
1560 Hobart St	F:2	5	Chinese Pistache	45	28	yes	yes	Dying, extensive trunk damage	1	500
484 E 1st Ave	F:1	5	Black Walnut	30	20	yes	yes	Dead	1	500
1904 Palm Ave	F:3	5	Silver Maple	45	14	yes	yes	Dead	1	500
533 Orange St	F:2	6	Black Walnut	40	26	yes	yes	Dying, decay at base Kim RSC 570-7724	1	500

City of Chico 2014 Tree Removal List

0 Extreme
 1 High
 2 Moderate

Address	Location:	zone	Species:	Height	DBH	Notice	Marked	Notes:	Priority Rating	Cost
1008 Alder St	F:2	6	English Walnut	25	24	yes	yes	Dying, extensive decay in main trunk	1	500
795 E 9th St	S:2 Poplar St	6	Camphor	55	26	yes	yes	Dying	1	500
1162 E 7th St	F:1	6	Sycamore	88	40	yes	yes	Extensive decay in upper scaffolds	1	500
564 El Reno	S:2 El Paso	7	Silver Maple	75	37	yes	yes	Dying, decay in upper scaffolds	1	500
564 El Reno	S:3 El Paso	7	Silver Maple	65	34	yes	yes	Dying, decay in upper scaffolds	1	500
241 Windrose Ct	F:1	7	Raywood Ash	45	19	yes	yes	Roots interfering with utilities and sidewalk	1	500
pic nick site #1 Bidwell Park	see map	8	Sycamore	90	57	yes	yes	Split trunk	1	500
47 trees @ \$500.00									total	23,500