

City of Chico 2015 Tree Removal List

0
1
2

Extreme
High
Moderate

Address	Location:	zone	Species:	Height	DBH	Notice	Marked	Notes:	Priority Rating	Cost
PRIORITY 1 TREES OCTOBER 2015										
1801 Salem St	F:1	1	Black Walnut	30	26	yes	yes	Dead	1	500
474 E 12th St	S:5 on Cypress	1	Tulip	30	10	yes	yes	Dead	1	500
474 E 12th St	S:3 on Cypress	1	Zelkova	45	34	yes	yes	Dying	1	500
314 W 14th St	F:1	1	Silver Maple	60	21	yes	yes	Dead	1	500
1515 Boucher St	F:1	1	Black Walnut	25	27	yes	yes	Dying, full of ivy	1	500
2451 Forest Ave	F:1	1	Hackberry	19	8	yes	yes	Roots causing major sidewalk hazard	1	100
2451 Forest Ave	F:3	1	Hackberry	18	9	yes	yes	Roots causing major sidewalk hazard	1	100
1613 Locust St	F:1	1	Black Walnut	25	20	yes	yes	Dying	1	500
1621 Locust St	F:2	1	Black Walnut	25	21	yes	yes	Dying	1	500
134 W 21st St	F:1	1	Norway Maple	30	11	yes	yes	Dying	1	500
1200 Park Ave	R:2 Oakdale St	1	Deodar Cedar	80	34	yes	yes	Dying	1	500
1851 Salem St	S:1 W 19th St	1	Black Walnut	50	23	yes	yes	Damaged trunk, splitting, bark coming off	1	500
1973 Belgium Ave	F:2	1	Cork Oak	25	13	yes	yes	Dead	1	500
1545 Park Ave	F:1	1	Pac Sun Maple	21	10	yes	yes	Dead	1	500
81 Skymountain Cir	R:1 Springfield	1	Redwood	65	22	yes	yes	Dead- trees are located on Springfield Dr.	1	500
17 Skymountain Cir	R:2 Springfield	1	Redwood	55	20	yes	yes	Dead- trees are located on Springfield Dr.	1	500
1459 Humboldt Rd	bike path	2	Ailanthus	50	33	yes	yes	Dead, along bike path at Hwy 99	1	500
890 Forest Ave	F:1	2	Mulberry	30	29	yes	yes	Dying	1	500
Vallombrosa @ Rey Way	Bidwell Park	3	Chinese Pistache	50	18	yes	yes	Damaged by a vehicle, invasive	1	500
665 Bryant	F:2	3	Chinese Pistache	60	28	yes	yes	Dying	1	500
1397 Longfellow	F:2	3	Modesto Ash	55	33	yes	yes	Trunk damage from split limb	1	500
1 Manor Cir	S:1 Lawton Dr	4	Tulip	70	36	yes	yes	Dead	1	500
1126 N Cedar St	F:1	5	Silver Maple	55	25	yes	yes	Dead	1	500
1126 N Cedar St	F:2	5	Silver Maple	60	32	yes	yes	Dead	1	500
438 W 2nd Ave	F:1	5	Silver Maple	45	24	yes	yes	Dying, decay, hollow	1	500
438 W 2nd Ave	F:2	5	Silver Maple	88	32	yes	yes	Dying, decay, hollow	1	500
448 W 2nd Ave	F:2	5	Silver Maple	18	15	yes	yes	Decay, interfering with utility lines	1	100
1417 Esplanade	F:2	5	Pin Oak	80	39	yes	yes	Damaged from large break out	1	500
2155 Algonkin Ave	F:2	5	Silver Maple	45	35	yes	yes	Dead	1	500
211 W 1st Ave	S:1 Magnolia	5	Modesto Ash	45	30	yes	yes	Dying, decay in upper scaffolds, utility lines	1	500
211 W 1st Ave	S:2 Magnolia	5	Modesto Ash	35	28	yes	yes	Dying, decay in upper scaffolds, utility lines	1	500
211 W 1st Ave	S:3 Magnolia	5	Modesto Ash	40	28	yes	yes	Dying, decay in upper scaffolds, utility lines	1	500
1200 Magnolia Ave	F:2	5	Black Walnut	35	20	yes	yes	Dead	1	500
1656 Palm Ave	F:1	5	Black Walnut	30	22	yes	yes	Dead	1	500
317 W 2nd Ave	F:2	5	Silver Maple	60	23	yes	yes	Dying, decay at base	1	500
326 W 1st Ave	F:1	5	Red Maple	18	14	yes	yes	Dying, decay in main trunk	1	100
326 W 1st Ave	F:3	5	Red Maple	45	22	yes	yes	Dying, decay in main trunk	1	500
1904 Laburnum Ave	F:1	5	Black Walnut	40	27	yes	yes	Dying	1	500
1904 Laburnum Ave	F:2	5	Black Walnut	50	22	yes	yes	Dying	1	500
2250 Fern Ave	F:1	5	English Walnut	35	34	yes	yes	Dying	1	500
254 Humboldt Ave	S:3 Wall St	6	Silver Maple	55	36	yes	yes	Dead	1	500

City of Chico 2015 Tree Removal List

0
1
2
Extreme
High
Moderate

Address	Location:	zone	Species:	Height	DBH	Notice	Marked	Notes:	Priority Rating	Cost	
438 Ash St	F:1	6	Tulip	55	25	yes	yes	Dying	1	500	
Greenway across the street 1066 Humboldt Rd		6	Valley Oak	55	25	yes	yes	Dead	1	500	
710 Walnut St	S:1 W 7th St	6	Black Pine	40	25	yes	yes	Dead	1	500	
711 Olive St	F:1	6	English Walnut	35	17	yes	yes	Dead	1	500	
178 E 2nd St	F:1	6	Hackberry	60	28	yes	yes	Trunk damage from split limb (2-bolts)	1	500	
607 W 3rd St	F:2	6	Silver Maple	65	34	yes	yes	Dead	1	500	
Humboldt Green Way	see map	6	Chinese Pistache	35	15	yes	yes	Extensive decay at base	1	500	
Humboldt Green Way	see map	6	Alder	50	19	yes	yes	Dead	1	500	
Humboldt Green Way	see map	6	Alder	50	18	yes	yes	Dead	1	500	
Humboldt Green Way	see map	6	Idaho Locust	45	11	yes	yes	Dying, decay at base	1	500	
Humboldt Green Way	see map	6	Idaho Locust	45	10	yes	yes	Dying, decay at base	1	500	
Humboldt Green Way	see map	6	Idaho Locust	45	10	yes	yes	Dying, decay at base	1	500	
Humboldt Green Way	see map	6	Black Locust	60	22	yes	yes	Dying, split trunk, decay at base	1	500	
4827 Chico River Rd WPCP	see map	6	Olive	21	12	yes	yes	Interfering with operations	1	500	
4827 Chico River Rd WPCP	see map	6	Olive	24	14	yes	yes	Interfering with operations	1	500	
4827 Chico River Rd WPCP	see map	6	Olive	24	24	yes	yes	Interfering with operations	1	500	
4827 Chico River Rd WPCP	see map	6	Olive	25	26	yes	yes	Interfering with operations	1	500	
655 E 4th St	S:3 Pine St	6	Silver Maple	45	32	yes	yes	Dying, decay in upper scaffolds, utility lines	1	500	
126 W 2nd St	F:1	6	Pear	30	10	yes	yes	Dead	1	500	
110 W 9th St	S:2 Oroville Ave	6	Red Maple	25	10	yes	yes	Dead	1	500	
Parking Lot 5 on E 1st St	see map	6	Valley Oak	35	16	yes	yes	Poor structure, high target area public hazard	1	500	
Parking Lot 5 on E 1st St	see map	6	Valley Oak	35	16	yes	yes	Poor structure, high target area public hazard	1	500	
Parking Lot 5 on E 1st St	see map	6	Valley Oak	55	20	yes	yes	Poor structure, high target area public hazard	1	500	
Parking Lot 5 on E 1st St	see map	6	Valley Oak	48	18	yes	yes	Poor structure, high target area public hazard	1	500	
Parking Lot 5 on E 1st St	see map	6	Catalpa	35	15	yes	yes	Invasive tree	1	500	
Parking Lot 5 on E 1st St	see map	6	Catalpa	35	16	yes	yes	Dead	1	500	
1460 Humboldt Rd	F:4	6	Raywood Ash	55	29	yes	yes	Dying	1	500	
1460 Humboldt Rd	F:5	6	Raywood Ash	40	14	yes	yes	Dying	1	500	
1460 Humboldt Rd	F:6	6	Raywood Ash	35	17	yes	yes	Dying	1	500	
1460 Humboldt Rd	F:7	6	Raywood Ash	30	12	yes	yes	Dead	1	500	
3005 Surrey Ln	S:1 W Shasta	7	Raywood Ash	60	32	yes	yes	Extensive root damage to sewerlines	1	500	
892 Lorinda Ln	F:1	7	Modesto Ash	55	35	yes	yes	Split Trunk attachments	1	500	
892 Lorinda Ln	F:2	7	Modesto Ash	55	31	yes	yes	Split Trunk attachments	1	500	
2 Oak Dr	S:2 White Ave	7	Silver Maple	55	46	yes	yes	Dying, extensive decay in upper scaffolds	1	500	
871 Lorinda Ln	F:1	7	Silver Maple	60	40	yes	yes	Dying, extensive decay in upper scaffolds	1	500	
860 Lorinda Ln	F:2	7	Silver Maple	65	35	yes	yes	Dead	1	500	
2 Emilio Way	F:1	7	Sycamore	45	19	yes	yes	Dying	1	500	
669 Henshaw Ave	F:1	7	English Walnut	35	29	yes	yes	Dying	1	500	
645 Henshaw Ave	F:2	7	English Walnut	45	29	yes	yes	Dying	1	500	
645 Henshaw Ave	F:4	7	English Walnut	35	28	yes	yes	Dead	1	500	
370 W Lassen Ave	F:1	7	Fir	70	27	yes	yes	Dead	1	500	
4-trees @ \$100, 78-trees @ \$500									82 total removals	total	39400